



PRE-REPAIR INSPECTION REPORT

Item / Description:	:	Toyota Rush <i>Corolla Altis</i>
Property Number:	:	POI197
Acquisition Cost :	:	Php1,137,000.00
Nature and Scope of Last Repair , if any :	:	PMS
Defects / Complaints	:	None
Findings	:	scheduled for PMS.
Recommendation	:	<input type="checkbox"/> For In-House Repair <input checked="" type="checkbox"/> For Job Out <input type="checkbox"/> For Replacement <input type="checkbox"/> For Disposal


Pre-Inspected by:



Rosehe D. Romero



Date



Riezel R. Umali


Date

POST - REPAIR INSPECTION REPORT

In-House Repair	For Job Out
Observations / Comments : _____ _____ _____ 	Name of Supplier : _____ P.O. No.: _____ Date of P.O. _____ Sales Invoice No. _____ Amount _____ Observations / Comments : _____ _____ _____

Post-Inspected by:

Roselle D. Romero

Date

Riezel R. Umali

Date